

Toll Free: 866-302-3284


www.iwpwaterjet.com



Identifying Shift Sensor Type

The IWP Shift Sensor F300-F0055-0000 has been discontinued and replaced with an updated sensor, F300-A0241-0000. For some applications this will require replacing the cable that connects the sensor to the waterjet pump. This document will help identify the correct parts for your application.

New Connector Style: If you have the screw together type (M12) three pin connector, the IWP Shift Sensor F300-A0241-0000 is a direct fit.



Old Connector Style: If you have the push together rubber 2 pin connector, you will need the IWP Sensor Update Kit F300-K0195-0000.

